UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,392,770 B2

Page 1 of 1

APPLICATION NO.: 10/577339
DATED: July 1, 2008
INVENTOR(S): Henglin Xiao

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 1: "technology in the art the" should read --technology in the art, the--. Column 3, line 4: "said tool air suction hood" should read --said cool air suction hood--. Column 4, line 10: "manufacturing cost The engine" should read --manufacturing cost. The engine--.

Column 4, line 49: "a scaling ring sealing a connection" should read --a sealing ring sealing a connection--.

Column 6, line 9 (claim 7): "magnet motor the cool" should read --magnet motor, the cool--.

Signed and Sealed this

Seventeenth Day of March, 2009

JOHN DOLL Acting Director of the United States Patent and Trademark Office